

# Strange Labor Rates

## Axles

**A1007** Remove axle bearings... **\$15.00 Pr.**

(a) Bearings and / or seals will be damaged and not be reusable.

(b) C-clip eliminator halves could be damaged, Strange will not be responsible.

(c) Axles that have been "tacked" or welded are not serviceable.

**A1008** Install axle bearings... **\$10.00 Pr.**

**A1008C** Install C-clip elim. kits... **\$10.00 Pr.**

**A1008R** Install retainer plates & axle bearings... **\$10.00 Pr.**

**A1009A** Turn down brake register (customer's axle) ("A" dimension)... **\$30.00 Pr.**

**A1009B** Move back bearing shoulder (customer's axle) ("B" dimension)... **\$30.00 Pr.**

**A1009F** Turn down axle flange outer diameter (customer's axle)... **\$30.00 Pr.**

**A1009O** One access hole in flange (customer's axle) (1" ID hole on 4.50" B.C.)... **\$30.00 Pr.**

**A1065** D & T Strange axles (customer's axle)... **\$80.00 Pr.**

*\*Axles must be sent-in stripped. No bearings or studs installed. \*Charge is for 1 bolt pattern. Tapped either 1/2x20 or 5/8x18.*

## Brakes

**B1260RB** Rebuild Strange single piston caliper (Labor only / parts extra)... **\$25.00 each**

**B2560RB** Rebuild Strange two piston caliper (Labor only / parts extra)... **\$25.00 each**

**B5000RB** Rebuild '95 to present Strange four piston caliper (Labor only / parts extra)... **\$40.00 ea.**

**B2799** Resurface Strange steel rotor... **\$20.00 ea.**

**B2800** Bake impurities out of contaminated carbon pads & rotors... **\$50.00 set**

Carbon only- remove aluminum hats.

## Housing

**H1130** Narrow housing using existing housing ends... **\$125.00**

**H1125** Modify housing ends for C-Clip Eliminator kit... **\$50.00**

**H1127** Check housing alignment... **\$50.00**

**H1123** Install H1121 or H1122 main caps on Chevy 12 bolt or Dana 60. (Labor only / parts extra)... **\$90.00**

**H1128** Install back brace on customers 9" housing. (Brace included)... **\$185.00**

**H1129** Install Filler & Drain plug on customers 9" housing. (Labor only / parts extra)... **\$40.00**

*Notes: All rates are assuming parts are ready for work to be performed- Any labor required to prep parts will be an additional charge.*

**Strange Engineering • 8300 North Austin Ave. • Morton Grove IL. 60053 •  
Phone # 847.663.1701 • Fax # 847.663.1702 • Web [www.strangeengineering.net](http://www.strangeengineering.net) •**



## Gears

**D3590** Set-up new ring & pinion in new Ford 9" and 12-bolt drop-out... **\$175.00**

**R5292** Set-up new ring & pinion in new Chevy 12 bolt (F-body) or Dana 60... **\$250.00**

**D3592** Gear change Ford 9" (Labor only / parts extra)... **\$195.00**

**D3594** Gear change Dana 60, Ford 8.8, Chevy 10 & 12 bolt (Labor only / parts extra)... **\$325.00**

**L7092** Gear change Strange Top-loader 9", 9.5", 10.50", & 12" (Labor only / parts extra)... **\$450.00**

**D3596** Lighten new ring gear. (At time of purchase)... **\$75.00**

**D3597** Lighten customer's ring gear... **\$100.00**

